

Is Your Crown WEATHERTITE?

Damaged chimney crowns are the leading cause of deterioration to masonry chimneys. On average, masonry chimney crowns need to be replaced every 7 to 10 years. Damage occurs due to the expansion and contraction of clay flue liners combined with the constant abuse from mother nature.

If left unattended, even minor cracking will allow water to penetrate into the chimney structure. This water will eventually cause masonry problems such as washed out mortar joints or spalling brick.

THE FLEXIBLE SOLUTION!

WeatherTite Masonry coatings are a proprietary blend of latex acrylics formulated for use over most exterior masonry. When properly applied, WeatherTite coatings will provide a resilient elastomeric, mortar like finish with superior weathering characteristics.



- *20 Year Limited Warranty*
- *100% Weatherproof*
- *Maintenance Free*
- *Permanently Flexible*
- *Natural Appearance*

WeatherTite products are the first choice of contractors to protect masonry, concrete & solve troublesome leaks

Flexible Crown / CrownTite

Trowel Grade

Brush Grade



Elastomeric Coating for repairing cracked and damaged chimney crowns
20 year warranty


FlashTite

Elastomeric Coating to repair damaged and leaking flashing around chimneys, vents and skylights
10 year warranty



WaterTite Masonry Water Repellent

Vapor Permeable; keeps water out of the masonry while allowing moisture vapor to escape
12 year warranty



Additional uses for WaterTite Masonry Water Repellent



"When only the best will do"